

## cut3LITE

### EN 388:2016+A1:2018 – odporność mechaniczna

Odporność na ścieranie	- 3 (zakres 0-4)
Odporność na przecięcie	- X (zakres 0-5)
Odporność na rozzerwanie	- 4 (zakres 0-4)
Odporność na przekucie	- 2 (zakres 0-4)
Odporność na przecięcie wg ISO 13997 TDM	- B (zakres A-F)

## Rękawice ochronne kat. II

WYPRODUKOWANO W SRI LANCE

EN 388:2016+A1:2018

EN ISO 21420:2020



3X42B



CAT II

Produkt jest zgodny z wymogami rozporządzenia PPE Regulation (EU) 2016/425

X – metoda badawcza jest nieodpowiednia dla rękawicy lub materiału z którego jest wykonana.

### Certyfikat badania typu UE

SATRA Technology Europe Limited  
Bracetown Business Park, Clonee, D15 YN2P, Dublin 15, Irlandia  
Numer jednostki notyfikowanej: 2777

### Użytkowanie

Rękawice przeznaczone do ochrony przed zagrożeniami mechanicznymi. Przed użyciem rękawic należy upewnić się, że nie posiadają one żadnych uszkodzeń mechanicznych. Uszkodzone rękawice należy wymienić na nowe. Przed przystąpieniem do pracy należy dobrać odpowiedni rozmiar rękawic. Wrażliwość dotykowa i czułość zmniejszają się przy złym dopasowaniu rękawic, co powoduje zmęczenie dłoni i palców. Zły rozmiar i złe dopasowanie prowadzi do słabej ochrony dłoni. Przed każdym użyciem rękawic należy sprawdzić, czy nie mają żadnych uszkodzeń fizycznych lub zanieczyszczeń. W przypadku jakichkolwiek uszkodzeń lub zanieczyszczeń rękawice należy wyrzucić. Zakładając rękawice należy upewnić się, że zarówno rękawica jak i dłoń są czyste, rękawica jest wolna od wad, które mogą utrudniać działanie, rozmiar rękawicy jest właściwy, oraz czy rękawica jest właściwie dopasowana do dłoni. Przy wyborze rękawic należy uwzględnić indywidualne warunki, środowisko i zawód. Używane rękawice zapewniają ochronę przed średnim ryzykiem, ale nie wolno ich używać jako ochrony przed chemikaliami, ogniem, wstrząsami i promieniowaniem. Nie należy używać w pozycji, w której istnieje ryzyko zaplądania się w wirujące części maszyny. Rękawice spełniające wymóg odporności na przebiecie mogą nie być odpowiednie do ochrony przed ostro zakończonymi przedmiotami, takimi jak igły podskórne. Rękawice odporne na przecięcie nie zapewniają całkowitej ochrony przed przecięciem. Żaden z materiałów ani procesów stosowanych w produkcji tych rękawic nie jest znany jako szkodliwy dla użytkownika. **Zdjęcie:** Rękawice należy zdjąć natychmiast gdy się zużyją lub ulegną uszkodzeniu. Połóż rękawice na obu dłoniach. Trzymając ręce w dół, by zapobiec kapaniu zanieczyszczeń na skórę lub ubranie, zdjąć pierwszą rękawicę tylko do palców - mankieta pozostanie nad dłonią. Chwyć drugą rękawicę pierwszą rękawicą i ściągnij ją. Pierwsza rękawica powinna się zsunąć. Trzymać rękawice tylko za wewnętrzną stronę - obszar nieskażony. Unikać dotykania zewnętrznej strony rękawicy.

### Przechowywanie

Przechowywać w suchym miejscu w temperaturze 5-25°C. Nie wystawiać na bezpośrednie działanie promieni UV. Nie wystawiać na działanie ozonu i otwartego ognia. Transport i przechowywanie tylko w opakowaniach dostawcy. Przy przechowywaniu zgodnie z zaleceniami, okres przydatności do użytkowania wynosi 3 do 5 lat od daty produkcji. Okres użytkowania nie jest ściśle określony i zależy od zastosowania oraz odpowiedzialności użytkownika za sprawdzenie przydatności rękawicy do zamierzonego zastosowania.

### Utylizacja rękawic

Zużyte rękawice należy utylizować zgodnie z lokalnymi przepisami. Firma SEMEX nie ponosi żadnej odpowiedzialności w tym zakresie. Używane rękawice mogą być zanieczyszczone skażeniami lub innymi niebezpiecznymi substancjami. Utylizacji ich należy dokonać zgodnie z obowiązującymi lokalnymi przepisami. W przypadku kontaktu z chemikaliami utylizować zgodnie z zaleceniami producenta chemikaliów.

### Czyszczenie rękawic

Nie należy pozostawiać zanieczyszczonych rękawic. Warunkiem ponownego użycia jest dokładne ich wyczyszczenie. Czyszczyć należy je z dala od wszelkich zagrożeń, a jeśli zanieczyszczenie stanowi potencjalne zagrożenie dla skóry dłoni lub nie jest usuwalne, rękawice należy delikatnie zsunąć unikając kontaktu dłoni ze szkodliwą substancją. Zużyte rękawice należy utylizować zgodnie z lokalnymi przepisami. Rękawice nadające się do prania są oznaczone odpowiednimi piktogramami. Właściwości wypranych rękawic mogą się różnić od przedstawionych w wynikach (EN 388:2016+A1:2018 - ryzyko mechaniczne). Rękawice mogą się kurczyć po praniu/czyszczeniu. Za właściwości ochronne używanych rękawic po praniu/czyszczeniu odpowiada użytkownik. Firma SEMEX nie ponosi żadnej odpowiedzialności w tym zakresie.

### Uwaga:

Wyniki testów powinny pomóc w doborze rękawic. Należy jednak zrozumieć, iż przedstawione właściwości rękawic są oparte na danych laboratoryjnych i mogą nie odzwierciedlać faktycznych warunków, w jakich rękawice będą używane. Odpowiedzialność, zarówno za dobór rękawic odpowiednich do rzeczywistych warunków jak i czas ich użytkowania, ponosi użytkownik, a nie producent. Test został przeprowadzony na części chwytnej rękawicy. Dalsze informacje można uzyskać od producenta.

LOT#20092023043



max=5

Deklaracja zgodności: <https://hfsafety.pl/>

Data produkcji: 01/2024

P.H.P.U. SEMEX Fertac, Huszno Sp. J.  
ul. Jagiellońska 101/105  
42-202 Częstochowa, Polska  
tel.: +48 34 39 06 735  
e-mail: bhp@semex.pl  
www.hfsafety.pl

ODDZIAŁ KRAKÓW  
ul. Biskupińska 28, budynek X  
30-732 Kraków  
tel.: +48 12 390 46 00  
e-mail: bhp.krakow@semex.pl  
www.hfsafety.pl



## cut3LITE

EN 388:2016+A1:2018- Mechanical risk

Abrasion resistance	- 3 (range 0-4)
Blade cut resistance	- X (range 0-5)
Tear resistance	- 4 (range 0-4)
Puncture resistance	- 2 (range 0-4)
ISO 13997 TDM	- B (range A-F)

## Safety gloves cat. II

MADE IN SRI LANKA

EN 388:2016+A1:2018



3X42B

EN ISO 21420:2020



CAT II

Product is in compliance with requirements of the PPE Regulation (EU) 2016/425

X - Test method appears not to be suitable for the glove design/material.

### EU-Type Examination Certificate

SATRA Technology Europe Limited  
 Bracetown Business Park, Clonee, D15 YN2P, Dublin 15, Ireland  
 Notified Body: 2777

### Product description:

Polyurethane palm coated machine knit gloves. The coating covers palm up to fingers.

Sizes: 6/XS, 7/S, 8/M, 9/L, 10/XL, 11/XXL

Packing: 12 pairs/bag 120 pairs/ carton

### Precautions for use

Gloves are intended to use against mechanical hazards. Before using the gloves make sure that there are no any mechanical damage. Damaged gloves should be replaced by new ones. Before working, you should choose the correct size of gloves. Tactile sensitivity and dexterity reduce with poor fitting of glove cause fatigue in hands and finger. Wrong size and poor fitting leads to poor hand protection. Check for any physical damages or contamination prior to each use of glove. Discard if there is any damage or contaminant. When donning the glove, please ensure that both glove and hand are clean, glove is free from defects that can hinder performance, glove size is right, and glove is properly fit on the contours and croches of fingers. The individual conditions, environment and occupation must be considered when selecting glove. Used gloves provide protection against medium risk but it's not allowed to use them as protection against chemicals, fire, shock and radiation. Do not use in position where there is a risk of entanglement in rotating parts of the machine. Gloves meeting the requirement for resistance to puncture may not be suitable for protection against sharply pointed objects such as hypodermic needles. These gloves resist cut but are not cut proof. None of the materials or processes used in the manufacture of these products is known to be harmful to the wearer. Do not subject to high speed or serrated blades. Removal: Remove the glove as soon as it wear off or damage. Loosen the gloves on both hands. Hold hands down to prevent dripping of material, product or contaminated water on your skin or clothing. While holding the gloves down, remove the first glove only up to the fingers - the cuff will remain over the palm. Grasp the second glove with the first glove and pull it off. The first glove should slide off. Hold the gloves by the inside only - the uncontaminated area. Avoid touching the outside of the glove.

**Removal:** Remove the glove as soon as it wear off or damage. Loosen the gloves on both hands. Hold hands down to prevent dripping of material, product or contaminated water on your skin or clothing. While holding the gloves down, remove the first glove only up to the fingers - the cuff will remain over the palm. Grasp the second glove with the first glove and pull it off. The first glove should slide off. Hold the gloves by the inside only - the uncontaminated area. Avoid touching the outside of the glove.

### Storage

Store in a cool, dry place. Do not expose to sources of ozone and open flames. Transport and storage only in supplier's packaging. Gloves should be stored at 5-25°C. When stored as recommended will not suffer change in mechanical properties 3 to 5 years from the date of manufacture. Service life cannot be specified and depends on the application and responsibility to user to ascertain suitability of the glove for its intended use.

### Disposal

Used gloves should be disposed by incineration or as per the regulation of local authorities. SEMEX does not bear any responsibility in this regard. Used gloves may be contaminated with infectious or other hazardous materials. Please dispose according to local authority regulations. In case of contact with chemicals, they should be disposed of in accordance with the chemical's manufacturer's instructions.

### Cleaning and care instructions

Gloves should not be left in contaminated condition if re-use is intended in which case gloves should be cleaned as far as possible provided no serious hazard exists, before removal from hand. When contaminant is not removable or presents a potential hazard, it is advisable to ease left and right gloves off alternately using the gloved hand so that the gloves are removed without the contaminant contacting bare hands. Used gloves should be disposed by incineration or as per the regulation of local authorities. Gloves that are suitable for washing are marked with appropriate pictograms. The performance characteristics of laundered gloves may differ from the results shown (EN 388:2016+A1:2018- Mechanical risk). Gloves may shrink after washing/cleaning. The user is responsible for the protective properties of the used gloves after washing or cleaning. SEMEX does not bear any responsibility in this regard.

**Please note:** Test results should help in the selection of gloves. However, it should be understood that the glove properties stated are based on laboratory data and may not reflect the actual conditions under which gloves will be used. User is responsible for the selection of suitable gloves for the actual conditions and the length of their application. Test is taken from palm area of the glove. Protection is limited to the palm only. Further information may be obtained from manufacturer.

LOT#20092023043



EU Declaration of Conformity: <https://hfsafety.pl/>

Date of production: 01/2024

P.H.P.U. SEMEX Fertacz, Huszno Sp. J.  
 ul. Jagiellońska 101/105  
 42-202 Częstochowa, Poland  
 tel.: +48 34 39 06 735  
 e-mail: bhp@semex.pl  
[www.hfsafety.pl](http://www.hfsafety.pl)

CRACOW BRANCH  
 ul. Biskupińska 28, budynek X  
 30-732 Kraków  
 tel.: +48 12 390 44 00  
 e-mail: bhp.krakow@semex.pl  
[www.hfsafety.pl](http://www.hfsafety.pl)

