

glassPROTECT2

EN 388:2016+A1:2018

Abrasion resistance	- 3 (range 0-4)
Blade cut resistance	- X (range 0-5)
Tear resistance	- 4 (range 0-4)
Puncture resistance	- 3 (range 0-4)
TDM cut resistance	- E (range A-F)
X-Not Tested / Blade blunted	

Safety gloves cat. II

EN 388:2016+A1:2018 EN ISO 21420:2020

**3X43E****CAT II**

Product is in compliance with requirements of the PPE Regulation EU 2016/425 and Regulation 2016/425 on personal protective equipment as amended to apply in GB.

For dulling during the cut resistance test (6.2), the coupe test results are only indicative while the TDM cut resistance test (6.3) is the reference performance result.

Sizes:
7/5, 8/M, 9/L, 10/XL, 11/XXL

Packing:
10 pairs/bag, 60 pairs/carton

EU - Type Examination Certificate:

CENTXBEL
Technologiepark 7, BE 9052 Gent, Belgium
Notified Body: 0493

UKCA Certificate:

BTTG® Unit 6 Wheel Forge Way, Trafford Park
Manchester, M17 1EH
United Kingdom
Approved Body No. 0338

Product description:

Cut resistant gloves coated with natural rubber latex.

Precautions for use

Used gloves provide protection against medium risk but it's not allowed to use them as protection against chemicals, fire, shock and radiation. They do not provide protection against extreme risks (cold, heat, fire). Suitability of the product is to be ascertained per each particular work application as part of the end users risk assessment program. Before working, you should choose the correct size of gloves. Wrong size and poor fitting leads to poor hand protection. When donning the glove, please ensure that both glove and hand are clean, glove is free from defects that can hinder performance, glove size is right, and glove is properly fit on the contours and crochets of fingers. Before using the gloves make sure that there are no any mechanical damage. Damaged gloves should be replaced by new ones. When an indication of hand hygiene precedes a contact that also requires glove usage, hand rubbing or hand washing should be performed before donning glove. Do not use in position where there is a risk of entanglement in rotating parts of the machine. Gloves meeting the requirement for resistance to puncture may not be suitable for protection against sharply pointed objects such as hypodermic needles. These gloves resist cut but are not cut proof. These gloves contain latex that can cause allergic reactions, in case of hypersensitivity seek medical advice. Removal: remove the glove as soon as it wear off or damage. Loosen the gloves on both hands. Hold hands down to prevent dripping of material, product or contaminated water on your skin or clothing. While holding the gloves down, remove the first glove only up to the fingers - the cuff will remain over the palm. Grasp the second glove with the first glove and pull it off. The first glove should slide off. Hold the gloves by the inside only - the uncontaminated area. Avoid touching the outside of the glove.

Storage

Store in a cool, dry place. Do not expose to sources of ozone and open flames. Gloves should be stored at 5-25° C. Transport and storage only in supplier's packaging. When stored as recommended will not suffer change in mechanical properties for 3 years from the date of manufacture. Service life cannot be specified and depends on the application and responsibility to user to ascertain suitability of the glove for its intended use.

Disposal

Used gloves should be disposed by incineration or as per the regulation of local authorities. Gloves that are suitable for washing are marked with appropriate pictograms. The user is responsible for the protective properties of the used gloves after washing or cleaning. SEMEX does not bear any responsibility in this regard. Used gloves may be contaminated with infectious or other hazardous substances. Disposal of them should be made in accordance with applicable local regulations. In case of contact with chemicals, they should be disposed of in accordance with the chemical's manufacturer's instructions.

Cleaning and care instructions



Not recommended for washing or cleaning.

Please note:

Test results should help in the selection of gloves. However, it should be understood that the glove properties stated are based on laboratory data and may not reflect the actual conditions under which gloves will be used. User is responsible for the selection of suitable gloves for the actual conditions and the length of their application. Test is taken from palm area of the glove.

EU and UK Declaration of Conformity

<https://hfsafety.pl/>

LOT#180820221394

Date of production: 09/2022

glassPROTECT2

EN 388:2016+A1:2018

Odporność na ścieranie	- 3 (skala 0-4)
Odporność na przecięcie	- X (skala 0-5)
Odporność na rozerwanie	- 4 (skala 0-4)
Odporność na przekucie	- 3 (skala 0-4)
TDM cut resistance	- E (skala A-F)

X-nie testowano / stępienie ostrza

Rękawice ochronne kat. II

EN 388:2016+A1:2018 EN ISO 21420:2020



3X43E



CAT II

Produkt jest zgodny z wymaganiami rozporządzenia o środkach ochrony indywidualnej UE 2016/425 i rozporządzenia 2016/425 w sprawie PPE w brzmieniu wprowadzonym do prawa brytyjskiego i zmienionym w celu stosowania w GB.

W przypadku tepienia ostrza podczas badania odporności na przecięcie, wyniki coup test są jedynie orientacyjne, punkt odniesienia stanowią wyniki testu TDM cut resistance.

Rozmiary:

7/S, 8/M, 9/L, 10/XL, 11/XXL

Opakowanie:

10 par/opak., 60 par/karton

Certyfikat badania typu UE:

CENTEXBEL

Technologiepark 7, BE 9052 Gent, Belgium

Jednostka notyfikowana: 0493

Certyfikat UKCA:

BTTG@ Unit 6 Wheel Forge Way, Trafford Park

Manchester, M17 1EH

United Kingdom

Organ uprawniony: 0338

Opis produktu:

Rękawice z dzianiny antyprecyzyjowej powlekanie marszczonym lateksem.

Użytkowanie

Stosowane rękawice ochronne stanowią ochronę przed średnim ryzykiem, jednakże nie wolno używać ich jako ochrony przed chemikaliami, ogniem, prądem i promieniowaniem. Nie stanowią ochrony przed ekstremalnym ryzykiem (zimno, gorąco, ogień). Przydatność produktu należy ustalić dla każdego konkretnego zastosowania w ramach oceny ryzyka przez użytkownika końcowego. Przed użyciem rękawic należy upewnić się, że nie mają one żadnych uszkodzeń mechanicznych. Uszkodzone rękawice należy wymienić na nowe. Przed wystąpieniem do pracy należy dobrać właściwy rozmiar rękawic. Niewłaściwy rozmiar i złe dopasowanie prowadzi do słabej ochrony dłoni. Podczas zakładania rękawicy należy upewnić się, że zarówno rękawica, jak i dłoń są czyste, rękawica jest wolna od wad, które mogą utrudniać jej działanie, rozmiar rękawicy jest właściwy, a rękawica jest odpowiednio dopasowana do dłoni. Jeżeli przed kontaktem wymagającym użycia rękawicy istnieje wskazanie do zachowania higieny rąk, przed założeniem rękawicy należy przetrzeć lub umyć ręce. Rękawice antyprecyzyjne nie zapewniają 100% ochrony przed przecięciem. Nigdy nie używać w przypadku, gdy istnieje ryzyko zacementowania przez części maszyn ruchomych. Rękawice spełniają wymagania odporności na przebiecie mogą nie być odpowiednie do ochrony przed ostro zakończonymi przedmiotami, takimi jak igły podskórne. Rękawice zawierają lateks, mogąny powodować reakcje alergiczne. W przypadku nadwrażliwości należy zasięgnąć porady lekarza. Zdejmowanie rękawic: zdjąć rękawicę, gdy tylko się zużyją lub ulegną uszkodzeniu. Poluzować rękawice na obu dłoniach. Trzymając rękawice w dół, zdjąć pierwszą rękawicę tylko do palców (mankiet pozostanie na dłoni), a następnie chwycić drugą rękawicę pierwszą rękawicą i ściągnąć ją. Pierwsza rękawica powinna się zsunąć. Trzymać rękawicę tylko za wewnętrzną stronę - obszar nieszakony. Unikać dotykania zewnętrznej strony rękawicy.

Przechowywanie

Przechowywać w czystym, suchym, wentylowanym pomieszczeniu w temperaturze 5-25 °C. Nie wystawiać na bezpośrednie działanie promieni UV. Nie wystawiać na działanie ozonu i otwartego ognia. Transport i przechowywanie tylko w opakowaniach dostawy. Przy przechowywaniu zgodnie z zaleceniami, okres przydatności do użytkowania wynosi 3 lata od daty produkcji. Należy pamiętać, że okres użytkowania nie jest ściśle określony i zależy od zastosowania oraz odpowiedzialności użytkownika za sprawdzenie przydatności rękawicy do zamierzonego zastosowania.

Utylizacja rękawic

Używane rękawice mogą być zanieczyszczone zakaźnymi lub innymi niebezpiecznymi substancjami. Utylizacji ich należy dokonać zgodnie z obowiązującymi przepisami i normami w zakresie ochrony środowiska. W przypadku kontaktu z chemikaliami utylizować zgodnie z zaleceniami producenta chemikalii.

Czyszczenie i konserwacja rękawic



Nie prac i nie czyścić.

Uwaga: Wyniki testów powinny pomóc w doborze rękawic. Należy jednak zrozumieć, iż przedstawione właściwości rękawic są oparte na danych laboratoryjnych i mogą nie odzwierciedlać faktycznych warunków, w jakich rękawice będą używane. Odpowiedzialność, zarówno za dobór rękawic odpowiednich do rzeczywistych warunków jak i czas ich użytkowania, ponosi użytkownik, a nie producent. Test został przeprowadzony na rękawic chwytnych rękawicy.

Deklaracja zgodności EU i UK

<https://hfsafety.pl/>

LOT#180820221394

Data produkcji: 09/2022

P.H.P.U. SEMEX Fertacz, Huszno sp. j.

ul. Jagiellońska 101/105,
42-200 Częstochowa, Poland
tel.: +48 34 39 06 735
e-mail: bhp@semex.pl
www.hfsafety.pl

ODDZIAŁ KRAKÓW

ul. Biskupińska 28, budynek X
tel.: +48 12 39 04 600
e-mail: bhp.krakow@semex.pl
www.hfsafety.pl