

PL

INSTRUKCJA UŻYTKOWANIA

flexyOIL

EN 388:2016+A1:2018 - Odporność mechaniczna

Odporność na ścieranie	- 4 (zakres 0-4)
Odporność na przecięcie	- 1 (zakres 0-5)
Odporność na rozdrabnianie	- 3 (zakres 0-4)
Odporność na przekucie	- 1 (zakres 0-4)
ISO 13997 TDM	- X (zakres A-F)

EN 407:2020 - Rękawice chroniące przed zagrożeniami termicznymi

Ograniczone rozprzestrzenianie płomienia	- X (zakres 0-4)
Ciepło kontaktowe	- 1 (zakres 0-4)
Ciepło konwekcyjne	- X (zakres 0-4)
Promieniowanie ciepłe	- X (zakres 0-4)
Małe rozpryski stopionego metalu	- X (zakres 0-4)
Duże ilości stopionego metalu	- X (zakres 0-4)
X - nie testowano	

X - metoda badawcza jest nieodpowiednia dla rękawicy lub materiału, z którego jest wykonana.

Deklaracja zgodności EU

ZVD Zawod za warstvo pri delu d.o.o.
Chengdajska cesta 25
1260 Ljubljana - Polje, Słowenia
Jednostka notyfikowana: 1493

Użytkowanie

Rękawice przeznaczone do ochrony rąk przed zagrożeniami zdefiniowanymi za pomocą piktogramów, zgodnie z zapisami zawartymi w normach EN lub EN ISO. Przydatność produktu należy ustalić dla każdego konkretnego zastosowania w ramach oceny ryzyka przez użytkownika końcowego. Przed użyciem rękawic należy upewnić się, że nie mają one żadnych uszkodzeń mechanicznych. Uszkodzone rękawice należy wymienić na nowe. Przed przystąpieniem do pracy należy dobrać właściwy rozmiar rękawicy. Wrażliwość dotykowa i zręczność zmniejszają się wraz z niewłaściwym dopasowaniem rękawic, powodując zmęczenie dłoni i palców. Niewłaściwy rozmiar i złe dopasowanie prowadzi do słabej ochrony dłoni. Podczas zakładania rękawicy należy upewnić się, że zarówno rękawica, jak i dłoń są czyste, rękawica jest wolna od wad, które mogą utrudniać jej działanie, rozmiar rękawicy jest właściwy, a rękawica jest odpowiednio dopasowana do dłoni. Jeżeli przed kontaktem wymagającym użycia rękawic istnieje wskazanie do zachowania higieny rąk, przed założeniem rękawic należy przetrzeć lub umyć ręce. Nie wystawiać na działanie otwartego ognia, jeśli rękawice mają pokazano odporność 1 lub 2 w zakresie palności. Odporność na ciepło kontaktowe maksymalnie do 100°C. Nigdy nie używać w przypadku, gdy istnieje ryzyko zapalenia przed części maszyn ruchomych. Rękawice spełniają wymagania odporności na przebieg mogą nie być odpowiednio do ochrony przed ostro zakończonymi przedmiotami, takimi jak igły podskórne. Niektóre rękawice zawierają materiały uważane za możliwe przyczyny alergii u osób wrażliwych i dlatego mogą powodować podrażnienie skóry i/lub reakcje alergiczne. W przypadku wystąpienia reakcji alergicznej należy niezwłocznie skontaktować się z lekarzem.

Zdejmowanie rękawic: zdjąć rękawicę, gdy tylko się zużyła lub uległa uszkodzeniu. Poluzować rękawicę na obu dłoniach. Trzymając rękawicę w dół, zdjąć pierwszą rękawicę tylko do palców (mankiet pozostanie na dłoni), a następnie chwycić drugą rękawicę pierwszą rękawicą i ściągnąć ją. Pierwszą rękawicę powinna się zsunąć. Trzymać rękawicę tylko za wewnętrzną stronę - obszar nieskażony. Unikać dotykania zewnętrznej strony rękawicy.

Przechowywanie

Przechowywać w czystym, suchym, wentylowanym miejscu. Nie wystawiać na bezpośrednie działanie promieni UV. Nie wystawiać na działanie ozonu i otwartego ognia. Transport i przechowywanie tylko w opakowaniach dostawczych. Przy przechowywaniu zgodnie z zaleceniami, okres przydatności do użytkowania wynosi 3 do 5 lat od daty produkcji. Okres użytkowania nie może być jednak ściśle określony i zależy od zastosowania oraz odpowiedzialności użytkownika za sprawdzenie przydatności rękawicy do zamierzonego zastosowania.

Utylizacja rękawic

Używane rękawice mogą być zanieczyszczone zakaźnymi lub innymi niebezpiecznymi substancjami. Utylizacja ich należy dokonać zgodnie z obowiązującymi przepisami i normami w zakresie ochrony środowiska. W przypadku kontaktu z chemikaliami utylizować zgodnie z zaleceniami producenta chemikaliów.

Instrukcja prania i czyszczenia

Przetrzeć wilgotną ściereczką. Nie należy używać zanieczyszczonych rękawic. Gdy zanieczyszczenia nie dają się usunąć lub stanowią potencjalne zagrożenie, zaleca się zdjąć lewą i prawą rękawicę na przemian używając dłoni w rękawiczkach, tak aby rękawice zostały zdjęte bez kontaktu z gołymi rękami. Rękawicę nadającą się do prania są oznaczone odpowiednim piktogramem. Za właściwości ochronne używanych rękawic po praniu/czyszczeniu odpowiada użytkownik. Firma Semex nie ponosi żadnej odpowiedzialności w tym zakresie. Wszystkie podane poziomy wyjątkowości dotyczą produktów w nowym stanie i nie mogą być zagwarantowane, jeśli produkt jest uszkodzony. Dlatego zaleca się, aby nie myć i nie czyścić produktu.

Uwaga:

Wyniki testów powinny pomóc w doborze rękawic. Należy jednak zrozumieć, iż przedstawione właściwości rękawic są oparte na danych laboratoryjnych i mogą nie odzwierciedlać faktycznych warunków, w jakich rękawice będą używane. Odpowiedzialność, zarówno za dobór rękawic odpowiednich do rzeczywistych warunków jak i czas ich użytkowania, ponosi użytkownik, a nie producent. Test został przeprowadzony na części chwytnej rękawicy. Ochrona jest ograniczona tylko do części dłoniowej. Więcej informacji można uzyskać od producenta.

Rękawice ochronne kat. II

WYPRODUKOWANO W PRC

EN 388:2016+A1:2018

EN 407:2020

EN 21420:2020



4131X



X1XXXX



Produkt jest zgodny z wymaganiami rozporządzenia o środkach ochrony indywidualnej UE 2016/425 i rozporządzenia 2016/425 w sprawie PPE w brzmieniu wprowadzonym do prawa brytyjskiego i zmienionym w celu stosowania w GB.

Opis produktu:

Rękawice poliestrowe dziane /ścieg 13/ z dwuwarstwową powłoką nitylową.

Rozmiary: 7/S, 8/M, 9/L, 10/XL, 11/XXL

Opakowanie: 12 par/120 karton

LOT #190920203629

Deklaracja zgodności: <https://hfsafety.pl/>

Data produkcji: 12/2022

EN

INSTRUCTIONS FOR USE

flexyOIL

EN 388:2016+A1:2018 – mechanical risk

Abrasion resistance	- 4 (range 0-4)
Blade cut resistance	- 1 (range 0-5)
Tear resistance	- 3 (range 0-4)
Puncture resistance	- 1 (range 0-4)
ISO 13997 TDM	- X (range A-F)

EN 407:2020 – Protection against thermal risks (heat and/or fire)

Limited Flame Spread	- X (range 0-4)
Contact Heat	- 1 (range 0-4)
Convective Heat	- X (range 0-4)
Radiant Heat	- X (range 0-4)
Small Splashes of Molten Metal	- X (range 0-4)
Large Quantities of Molten Metal	- X (range 0-4)
X (range 0-4)	- X (range 0-4)

X - Test method appears not to be suitable for the glove design/ material.

EU - Declaration of Conformity

SZVD Zавод за varstvo pri delu d.o.o.
 Chengdujska cesta 25
 1260 Ljubljana - Polje, Slovenija
 Notified body: 1493

Precautions for use

Gloves intended for hand protection against hazards defined by pictograms, according to the provisions of EN or EN ISO standards. Suitability of the product is to be ascertained per each particular work application as part of the end users risk assessment program. Before working, you should choose the correct size of gloves. When donning the glove, please ensure that both glove and hand are clean, glove is free from defects that can hinder performance, glove size is right, and glove is properly fit on the contours and crotches of fingers. Tactile sensitivity and dexterity reduce with poor fitting of glove cause fatigue in hands and finger. Wrong size and poor fitting leads to poor hand protection. Before using the gloves make sure that there are no any mechanical damage. Damaged gloves should be replaced by new ones. When an indication of hand hygiene precedes a contact that also requires glove usage, hand rubbing or hand washing should be performed before donning glove. Maximum use till 100°C. Do not expose to open flame, if the glove has a performance level 1 or 2 in burning behavior. Do not use in position where there is a risk of entanglement in rotating parts of the machine. Gloves meeting the requirement for resistance to puncture may not be suitable for protection against sharply pointed objects such as hypodermic needles. Some gloves made contain materials considered as the possible cause of allergies in susceptible persons, and which may therefore lead to skin irritation and/or allergic reactions. In the event of an allergic reaction, consult a doctor immediately.

Removal: remove the glove as soon as it wear off or damage. Loosen the gloves on both hands. Hold hands down to prevent dripping of material, product or contaminated water on your skin or clothing. While holding the gloves down, remove the first glove only up to the fingers - the cuff will remain over the palm. Grasp the second glove with the first glove and pull it off. The first glove should slide off. Hold the gloves by the inside only - the uncontaminated area. Avoid touching the outside of the glove.

Storage

Store in a cool, dry place. Do not expose to sources of ozone and open flames. Transport and storage only in supplier's packaging. When stored as recommended will not suffer change in mechanical properties for up to 3-5 years from the date of manufacture. Service life cannot be specified and depends on the application and responsibility to user to ascertain suitability of the glove for its intended use.

Disposal

Used gloves should be disposed by incineration or as per the regulation of local authorities. Please dispose according to local authority regulations. In case of contact with chemicals, they should be disposed of in accordance with the chemical's manufacturer's instructions.

Washing & cleaning instructions:

Wipe with wet cloth. Gloves should not be left in contaminated condition. When contaminant is not removable or presents a potential hazard, it is advisable to ease left and right gloves off alternately using the gloved hand so that the gloves are removed without contacting bare hands. Used gloves should be disposed by incineration or as per the regulation of local authorities. Gloves that are suitable for washing are marked with appropriate pictograms. The user is responsible for the protective properties of the used gloves after washing or cleaning. SEMEX does not bear any responsibility in this regard. All performance levels quoted are for products in new condition and cannot be guaranteed if the product is laundered. Hence it is recommended that the product should not be washed and cleaned.

Please note: Test results should help in the selection of gloves. However, it should be understood that the glove properties stated are based on laboratory data and may not reflect the actual conditions under which gloves will be used. User is responsible for the selection of suitable gloves for the actual conditions and the length of their application. Test is taken from palm area of the glove. Further information may be obtained from manufacturer.

LOT #190920203629

EU Declaration of Conformity: <https://hfsafety.pl/>

Date of production: 12/2022

P.H.P.U. SEMEX Fertaciz, Huzszo Sp. J.
 ul. Jagiellońska 101/105
 42-202 Częstochowa, Poland
 tel.: +48 34 39 06 735
 e-mail: bhp@semex.pl
www.hfsafety.pl

CRACOW BRANCH
 ul. Biskupińska 28, budynek X
 30-732 Kraków, Poland
 tel.: +48 12 390 46 00
 e-mail: bhp.krakow@semex.pl
www.hfsafety.pl



Safety gloves cat. II

MADE IN PRC

EN 388:2016+A1:2018



4131X

EN 407:2020



X1XXXX

EN 21420:2020



Product is in compliance with requirements of the PPE Regulation EU 2016/425 and Regulation 2016/425 on personal protective equipment as amended to apply in GB.

Product description:

13 gauge polyester gloves with double dip nitrile.

Sizes: 7/S, 8/M, 9/L, 10/XL, 11/XXL

Packing: 12 pairs/120 carton